




ASSEMBLY OF SHIELD AND BRACKET TO BLOWER MOUNT PLATE

| | | | | | |
|--|-----|-----------------|---------------------------------------|-----------------|-----------|
| <div><div><div><div><div><div></div></div></div><div><div></div><div></div></div></div><div><div>TOMMY</div><div>CAR WASH SYSTEMS</div></div></div><div>581 Ottawa Ave. Holland, MI 49423 616-494-0771-tommycarwash.com</div><div>DIMENSIONS: UNLESS STATED OTHERWISE: ALL DIMENSIONS ARE IN INCHES TOLERANCES: .X:± 0.1 .XX:± 0.01 .XXX:± 0.005 ANGLE:± 0.5</div><div>CONFIDENTIAL WARNING: THIS SHEET CONTAINS AND CONSTITUTES CONFIDENTIAL INFORMATION, IMAGES AND TRADE SECRETS OF TOMMY CAR WASH SYSTEMS. ANY UNAUTHORIZED USE OR PORTION THEREOF, IS STRICTLY PROHIBITED. THIS WORK IS THE EXCLUSIVE PROPERTY OF TOMMY CAR WASH SYSTEMS. ALL RIGHTS RESERVED</div></div> | - | | PART NUMBER: P-B2065-K | | REV. - |
| | - | | DESCRIPTION: | | |
| | - | | MATERIAL: Material <not specified> | FINISH: | |
| | - | | DRAWN BY: | DATE: | |
| | - | | APPROVED BY: | DATE: | |
| | - | INITIAL RELEASE | SCALE 1:5 | SHEET 1 OF 3 | |
| | NO. | REVISION/ISSUE | DATE | | |




NOTE - DO NOT FULLY TIGHTEN THESE UNTIL THE BRACKETS
ARE MOUNTED TO THE BLOWER MOUNT PLATE



| | | | |
|--|---------------------------|-----------------|-----------|
|  581 Ottawa Ave. Holland, MI 616-494-0771 tommycarwash.com UNLESS OTHERWISE SPECIFIED TOLERANCES: X: ± 0.1 .XX: ± 0.01 .XXX: ± 0.005 ANGLE: ± 0.5 | PART NUMBER: P-B2065-K | | REV. - |
| | DESCRIPTION: | | |
| | DRAWN BY: | DATE: | |
| | SCALE 1:5 | SHEET 2 OF 3 | |
| | | | |

GENERAL NOTES:


- THE TRAY IS SLOTTED TO ALLOW FOR ADJUSTMENT FOR OPTIMAL PROTECTION. DO NOT FULLY TIGHTEN THE FASTENERS THAT RETAIN THE SHIELD TO THE MOUNT BRACKETS UNTIL THE BRACKETS ARE MOUNTED TO THE BLOWER MOUNT PLATE AND ADJUSTED TO THE PROPER POSITION. SEE THE IMAGE BELOW, THE ARROWS REFER TO THE ADJUSTMENT DIRECTIONS.



- IN SOME BLOWER CONFIGURATIONS THERE MAY BE AN EXTREME NOZZLE ANGLE THAT MAY RESTRICT ADJUSTABILITY. IF THE BLOWER NOZZLE IS LIMITING THE ADJUSTMENT OF THE SHIELD, TUCK THE EDGE OF THE SHIELD INTO THE "CREVICE" (SEE ARROW IN "DETAIL A" BELOW) AS FAR AS POSSIBLE TO MAXIMIZE PROTECTION



DETAIL A

| | | | |
|--|---------------------------|-----------------|-----------|
|  581 Ottawa Ave. Holland, MI 616-494-9771 tommycarwash.com UNLESS OTHERWISE SPECIFIED TOLERANCES: X:± 0.1 .XX:± 0.01 .XXX:± 0.005 ANGLE:± 0.5 | PART NUMBER: P-B2065-K | | REV. - |
| | DESCRIPTION: | | |
| | DRAWN BY: | DATE: | |
| | SCALE 1:5 | SHEET 3 OF 3 | |